

The Work at Height Regulations 2005 set out the measures that should be taken to prevent falls when working at height is unavoidable. Together, these form the Hierarchy of Control Measures, which are shown in the diagram below.

